

Basic Vehicle Condition Guide

Report ID: 18,874,470

Version:


18 Jan 2019 Created:

Fail N/A

Make: Model: Daewoo Nubira **Body Style:** Wagon Year: 2005 Registration: HNH344 Reg Expiry: 18 Mar 2019 **WoF Expiry: Odometer:** 22 May 2019 172,446 Kms **Good No:** 18874470 VIN: KLAJF35ZE3K886616 **Next Service:** 180000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No Kms:

| Engine | | | |
|------------------------------|---------------------------------------|-----------|----------|
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | l deptl | n of tyre | es) |
| Left front | | 4 | mm |
| Right front | 4 | | mm |
| Left rear | · | | mm |
| Right rear | 5 mm | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | I |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | | ~ | |
| Window winder FL | ~ | | |
| Window winder FR | | | |
| Window winder RL | V | | |
| Window winder RR | 1 | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | · | | |
| Number of keys | 1 | 1 | <u> </u> |
| Central locking | · / | | |
| Remote locking | - | | ~ |
| Sat. Nav. (basic test only) | | | <u>,</u> |
| Poversing sames | | | |

I have read and understood this condition guide.

Name:

Signature:

18 Jan 2019

Date: