

Report ID: 18,875,604 Version: 1 27 Jan 2019 Created:

Make:	Holden	Model:	UTE	Body Style:	Utility		Pass	Fail	N/A
Year:	2004	Registration:	CFE278	Reg Expiry:	30 Apr 2019	Engine		-	
WoF Expiry:	01 Feb 2020	Odometer:	220,832 Kms	Good No:	18875604	Oil level	~		
VIN:	6G1YK42A54L216341	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance		~	
	port is not a warranty		C 1 11	D	1 P 41 1	Noise	~	•	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~	•	
Key:	SC	-0	S	-161-	SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			715		Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack				+	S SC	Clutch			~
P = pin dent	Ho					CV joints			~
* = decals	scw 916			The	ELTP SP	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significan	t scuffs S	$- \emptyset$	S	JUS	SP	Performance	~		
		Note: som	ne defects & blemishe	s mav not be disc	blaved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			 (کد
Tools for jack are missing.									mm
						Right front	5.	-	 mm
						Left rear			mm
Conditions During Rodu Inspection						Right rear			 mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Coolant system needs a flush. Pulley belt on front of engine is starting to perish. Front brake disc/rotors						Suspension performance			
	r oil leak coming from f					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	~		
General Comments						Window winder RL			~
Engine has						Window winder RR			~
						Rear view mirrors	~		–
						Radio (basic test only)	~		
						CD (basic test only)	~		<u> </u>
						Number of keys	2		
Pood Com	ditions During Tor					Central locking	2		
Road Con	ditions During Tes	t Drive:	Dry			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								
Inspecte	d by: Jason Young	Date: 25 Jan 20	19						

I have read and understood this condition guide.

Name:

Signature: