

Basic Vehicle Condition Guide

Report ID: 18,876,129


Version: 1

21 Jan 2019 Created:

Make: Model: Holden Viva **Body Style:** Hatchback Year: 2006 Registration: DCZ660 Reg Expiry: 01 Mar 2019 **Odometer:** WoF Expiry: 20 May 2019 106,716 Kms **Good No:** 18876129 VIN: KL3NA48BJ6K321503 Next Service: 106716 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

All Four Door Handles paint peeling,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil seepage lower engine area, Exhaust System Surface Rust,

Interior Comments				
Seats	R/F Seat Burn Holes			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

Service Due,

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Chris Buckley

Evidence of Cam Belt Replacement: No Kms:

		1		
	Pass	Fail	N/A	
Engine		ı		
Oil level	~			
Smoke & fumes	<i>V V V</i>			
Performance	~			
Noise	~			
Cooling System		ı		
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission		ı		
Operation	~			
Noise	-			
Clutch			-	
CV joints	~			
Wheel bearings	~			
Brakes		1		
Performance	~			
Hand Brake	~	_		
Tyres (lowest observed tread	d depth	of tyre	es) 	
Left front	4.0		mm	
Right front	4.0		mm	
Left rear	8.0		mm	
Right rear	8.0		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation		~		
Electrical / Accessories		ı		
Head lights	/			
Tail lights	~			
Indicators	\(\triangle \)			
Dashboard warning lights				
Wipers (front & rear)	\(\times \) \(\t			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR				
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
		i .		

I have read and understood this condition guide.

Name:

Signature:

21 Jan 2019

1

Reversing camera