


<b>Make:</b>	Toyota	<b>Model:</b>	Landcruiser	<b>Body Style:</b>	SUV
<b>Year:</b>	1994	<b>Registration:</b>	LRL471	<b>Reg Expiry:</b>	15 Jul 2019
<b>WoF Expiry:</b>	24 Apr 2019	<b>Odometer:</b>	319,446 Kms	<b>Good No:</b>	18876164
<b>VIN:</b>	JT721PJ7508009288	<b>Next Service:</b>	315,000kms	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Rust at top of left side C pillar, by roof seam. Snorkel housing has a crack in it. Left side wing mirror arm has a crack in it, has been taped up.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Minor oil leak from around gearbox. Minor oil leak from left side of engine.

## Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## General Comments

Winch not tested, as can't find winch remote. Black seat cover that has been fitted over seat covers has a hole in it, base of drivers seat.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 274,169

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.4	mm	
Right front	12.0	mm	
Left rear	6.8	mm	
Right rear	6.8	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking			✓
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 25 Jan 2019

I have read and understood this condition guide.

Name: .....

Signature: .....