

Report ID: 18,876,769


Version: 1

24 Jan 2019 Created:

Make:	Rover	Model:	MG	Body Style:	Convertible
Year:	1996	Registration:	ZI4569	Reg Expiry:	16 Jul 2019
WoF Expiry:	18 Jul 2019	Odometer:	58,709 Kms	Good No:	18876769
VIN:	SARRDWBGBAD00080	Next Service:	?	Service History	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil level is low on dip stick. Front brake disc/rotors worn. Minor oil leak from right side of engine & from between engine & gearbox.

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Engine oil level is low is on engine dip stick. Flat spot/out of round left rear alloy rim, both rear tyres have uneven tread wear & tyres out of round. Radio/cd player is not working. A/C not getting cold, needs attention.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jason Young

Evidence of Cam Belt Replacement: Kms:

24 Jan 2019

	Pass	Fail	N/A
Engine			
Oil level		~	
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System	•	•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	•
Operation	~		
Noise	~		
Clutch	~		
CV joints	\(\times \)		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5	.8	mm
Right front	6	.0	mm
Left rear	6.0		mm
Right rear	6	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	> > > > > > > > > > > > > > > > > > >		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)		~	
CD (basic test only)		~	
Number of keys	2	<u> </u>	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~
		l	

I have read and understood this condition guide.

Name:			