

## **Basic Vehicle Condition Guide**

Report ID: 18,877,123

Pass

Version:

**Engine** 

Oil level

Created: 21 Jan 2019


Fail

N/A

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2002 Registration: BAP626 Reg Expiry: 09 Dec 2019 WoF Expiry: **Odometer:** 09 Oct 2019 121,476 Kms **Good No:** 18877123 VIN: KMHBT31HR3U00995: Next Service: 141000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

L/H Sill Dent,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Surface rust on under body.

Interior Comments	<u>s</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

Genera	l Comments

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes Kms: 103,000

Smoke & tumes	<b>/</b>		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			ı
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		l	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5	.0	mm
Right front	5.0		mm
Left rear	7	7.0	
Right rear	7.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	
Operation	~		
Electrical / Accessories	•		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	<b>V</b>		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Inspected by:	Chris Buckley	Date:	21.	Jan	20	)19
---------------	---------------	-------	-----	-----	----	-----