

Report ID: 18,878,866 Version: 1 24 Jan 2019 Created:

Make:	Mazda	Model:	Roadster	Body Style:	Convertible		Pass	Fail	N/A
Year:	2003	Registration:	DSJ670	Reg Expiry:	15 Jun 2019	Engine			
WoF Expiry:	29 Sep 2019	Odometer:	172,992 Kms	Good No:	18878866	Oil level	~		
VIN:	7A8C12Y0707300946	Next Service:	175000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	is can be arranged fo	or an additional C	narge.	Coolant condition	~		
						Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				10		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	~		
P = pin dent	PdB				2416	CV joints			~
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significan		C				Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
<u>2007 aspector connerto</u>						Tyres (lowest observed tread depth of tyres)			
						Left front 7			mm
						Right front	7	7	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Dry						Right rear	4		mm
						Spare Yes			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicm: Combelt						Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
	or Cam Beit Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 24 Jan 2019									

I have read and understood this condition guide.

Name:

Signature: