

Basic Vehicle Condition Guide

Report ID: 18,880,182

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 28 Jan 2019

Pass

~

~

/


Fail

N/A

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2014 Registration: HUG950 **Reg Expiry:** 26 Feb 2019 WoF Expiry: **Odometer:** 23 Jan 2020 61,148 Kms **Good No:** 18880182 VIN: MR0EZ12G604158638 **Next Service:** 60000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LH tail light lens cracked

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

Kms:

Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch / CV joints 1 Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 3 mm Left rear 2.5 mm Right rear 2.5 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 3 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1

Inspected by:	Xinghui Lin	
	·	

28 Jan 2019

Date: