

Basic Vehicle Condition Guide

Report ID: 18,881,264

Version: 2


Created: 18 Feb 2019

Pass Fail N/A

Make: Model: Ford Mondeo **Body Style:** Wagon Year: 2015 Registration: JKF640 Reg Expiry: 27 Apr 2019 **Odometer:** WoF Expiry: **Good No:** 30 Oct 2019 98,170 Kms 18881264 VIN: **Next Service:** WF0FXXWPCFFY5997 103377 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Steering wheel worn

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Bobby Zhong

Evidence of Cam Belt Replacement: No

Kms:

| | Pass | Fail | N/A | |
|------------------------------|-----------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\triangle \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | | • | |
| Coolant condition | ~ | | | |
| Performance | V V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | ı | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | l | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | Į. | 5 | mm | |
| Right front | 2 | 2 | mm | |
| Left rear | (| 5 | mm | |
| Right rear | | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | | | | |
| Dashboard warning lights | V | | | |
| Wipers (front & rear) | | | | |
| Window winder FL | \(\times \) | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | V | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | L | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| Reversing camera | ~ | | | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature:

18 Feb 2019

Date: