

Report ID: 18,881,684 Version: 1 08 Feb 2019 Created:

Make:	Toyota	Model:	Caldina	Body Style:	SUV		Pass	Fail	N/A	
Year:	2005	Registration:	GLP558	Reg Expiry:	29 Jan 2019	Engine			I	
WoF Expiry:	08 Feb 2020	Odometer:	157,835 Kms	Good No:	18881684	Oil level	~			
VIN:	7AT0H624X12023710	Next Service:		Service Histor		Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	hoon dismonthed on	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
			P SC S D			Performance	~			
Key:	S	-0	PSC S D	-01-	P SC	Radiator / Hoses (visual)	~			
S = scratch	TE			NOG	Tan	Transmission				
D = dent R = rust	sc			715		Operation	~			
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HE				74116	CV joints	~			
* = decals	- Alt	10		10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w = significan			SC S D SC			Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)				
		,				Left front	4	Ļ	mm	
						Right front	4	Ļ	mm	
						Left rear	4	ŀ	mm	
Conditions During Body Inspection: Dry						Right rear	4 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories	/ Accessories			
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	ru 🧊					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Donovan Matara Date: 08 Feb 2019										

I have read and understood this condition guide.

Name:

Signature: