

Report ID: 18,882,103 Version: 1 19 Feb 2019 Created:

Make:	Ford	Model:	Falcon	Body Style:	Sedan		Pass	Fail	N/A
Year:	2003	Registration:	BTJ337	Reg Expiry:	14 Oct 2019	Engine	1		
WoF Expiry:	24 Jan 2020	Odometer:	286,079 Kms	Good No:	18882103	Oil level	~		
VIN:	6FPAAAJGSW3P57634	Next Service:	?	Service Histor	y: No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	P SC	-0	ls	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S = suct S SC D D S						Operation	~		
R = rust PT = paint def				\prod	JUIL	Noise	~		
C = crack				+	R	Clutch			~
P = pin dent					세비	CV joints			~
* = decals	sc 916			The	ETTE	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S S S S S S S S S S S S S S S S						Performance	~		
		Note: son	he defects & blemishes	s may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	 >s)
Steering wheel cover worn.									 mm
						Right front			mm
						Left rear		.3	mm
						Right rear			
Conditions During Body Inspection: Wet							4.8 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	spection done on vehicl	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	-		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights		~	
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
General Comments Coolant system needs a flush. ABS light coming up on dash display. Hole & rip in right side base of rear seat.					Window winder RL	~			
Vehicle lock itself if left unlocked. One of key remotes are not working to lock & unlock vehicle. Screw holes in						Window winder RR	~		
left side of o	centre console.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Ti	ming Mechanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspector	d by: Jason Young					Date: 12 Feb 20	19		
							-		

I have read and understood this condition guide.

Name: