

Report ID: 18,882,518


Version: 2

Created: 10 Feb 2019

| Make: | Nissan | Model: | Navara | Body Style: | Utility |
|-------------|------------------|---------------|-------------|-----------------|-------------|
| Year: | 2012 | Registration: | GNG344 | Reg Expiry: | 25 Mar 2019 |
| WoF Expiry: | 10 Jan 2020 | Odometer: | 141,304 Kms | Good No: | 18882518 |
| VIN: | MNTCPGD22A000069 | Next Service: | 150,200 | Service History | /: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | | |
|--------------------------|------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Good | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Name:

Mathew Varghese Inspected by:

| | Pass | Fail | N/A |
|------------------------------|----------|---------|---------|
| Engine | | | - |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | V | | |
| Noise | ~ | | |
| Cooling System | | | 1 |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | ı | | 1 |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | 1 | i . | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | es) |
| Left front | | 5 | mm |
| Right front | | 5 | mm |
| Left rear | 3 | 3 | mm |
| Right rear | 3 | 3 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ' | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Date: 10 Feb 2019

Signature: