

Report ID: 18,882,853 Version: 1 05 Feb 2019 Created:

Signature:

Make:	Subaru	Model:	Legacy	Body Style:	Wagon		Pass	Fail	N/A	
Year:	1995	Registration:	XG6756	Reg Expiry:	18 Mar 2019	Engine		<u> </u>		
WoF Expiry:	16 Mar 2019	Odometer:	272,521 Kms	Good No:	18882853	Oil level	~			
VIN:	7A8GF0B0798099240	Next Service:		Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		C 1 1	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	S SC	-0	S SC S SC		S SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission			<u> </u>	
D = dent						Operation	~			
R = rust				\int	THIA	Noise	•	~		
PT = paint defe C = crack				$+ \vee$	S PT SC	Clutch	~	•		
P = pin dent	Ho					CV joints	~			
* = decals	S PT SC			AL-	ELTR SSC	Wheel bearings	~			
SC = stone chips							Brakes			
W = significant scuffs S SC S SC S SC S SC S SC									1	
		Note: com				Hand Brake	v		-	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							I donth	ofture		
Only one remote working						Tyres (lowest observed tread depth of tyres) Left front 3.1				
							3.		mm	
						Right front	5		mm	
						Left rear			mm	
Conditions During Body Inspection: Dry						Right rear	0.0		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
						Suspension				
Engine oil le	EdK					Suspension performance	~			
						Steering performance	~			
Shock abs							~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Average						Electrical / Accessories				
Seats	/weitige					Head lights	~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~		<u> </u>	
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~		\mid	
Concerto						Window winder FR	~		<u> </u>	
General Comments Thrust bearing noise						Window winder RL	~			
	ing noise					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	<			
						Remote locking	<			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 23	3,196	Reversing camera			~	
1	Inspected by: Ian Dunn Date: 30 Jan 2019									
Inspected by. Ian Dunin Date: 30 Jan 2019										

I have read and understood this condition guide.

Name: