

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S S Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ S SC \* = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs SD Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Rear bumper misaligned Left front mm 8.0 **Right front** 8.0 mm Left rear 5.0 mm **Right rear** 5.0 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Average Head lights Seats 1 Tail lights ~ Average Carpets Indicators ~ Average Dashboard warning lights 1 Panels Wipers (front & rear) 1 Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan

30 Jan 2019 Date:

Reversing camera

Report ID: 18,883,788 Version: 1 Created: 14 Feb 2019

Fail

Pass

~

V

V

V

Oil level

Noise

Smoke & fumes

Performance

N/A

I have read and understood this condition guide.

Name: .....

Signature: .....

~