

Report ID: 18,883,800 Version: 2 13 Feb 2019 Created:

Signature:

Make:	Holden	Model:	Rodeo 4X4	Body Style:	Utility		Pass	Fail	N/A	
Year:	2005	Registration:	CWY736	Reg Expiry:	30 May 2019	Engine				
WoF Expiry:	04 Oct 2019	Odometer:	250,812 Kms	Good No:	18883800	Oil level	~			
VIN:	MPATFS77H5H549264	Next Service:		Service History	V: No	Smoke & fumes	~			
			- ,		-	Performance	~			
	port is not a warranty		с I II			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	S SC	-0	SD S		s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation	~			
R = rust PT = paint def				í l	THA	Noise	~			
C = crack					SC	Clutch	~			
P = pin dent	HIC					CV joints	~			
* = decals	SDSC 916			-NL	ETTP 5	Wheel bearings	~			
SC = stone chi		LO		1al	& <u> </u>	Brakes	•			
W = significan	t scuffs SC	$- \emptyset$	IS IS		Is	Performance	~			
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			<u> </u>	
Remote locking not working.									mm	
						Right front		.0	mm	
						Left rear	-		mm	
Conditions During Rody Inspections Dry						Right rear			mm	
Conditions During Body Inspection: Dry						Spare				
Under Carriage & Under Bonnet Inspection Comments					Spare Yes Suspension					
LR shock at	osorber weeping oil.					Suspension performance	~			
	surface rust.					Steering performance	~			
Play in Dotr	front wheelbearings.					Shock absorbers	~			
						Air Conditioning / Heater			<u> </u>	
						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	A					Tail lights	~		-	
Carpets	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~		+	
						Wipers (front & rear)	~			
Dashboa	rd Average					Window winder FL	~		+	
						Window winder FR	~		+	
General (<u>Comments</u>					Window winder RL	~			
Drivebelt n	oisy.					Window winder RR	~		+	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~		+	
						Number of keys	1		<u> </u>	
Road Conditions During Test Drive: Dry Central locking							· •			
			ر الع 			Remote locking		~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)		-	~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
[
Inspected by: Dion Mair Date: 12 Feb 2019										

I have read and understood this condition guide.

Name: