



Turners Certified Imports 50 Point Check

Report ID: 18,884,276
Version: 1
Created: 31 Jan 2019

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

| | |
|----------------|------------------------|
| Make: Toyota | Body Style: Wagon |
| Model: Corolla | Odometer: 90,416 Kms |
| Year: 2013 | VIN: 7AT0H607X19010030 |

| | |
|------------|---------|
| Seats: | Good |
| Carpets: | Good |
| Panels: | Good |
| Dashboard: | Average |

Under Carriage & Under Bonnet Inspection Comments

| | |
|------------------------------------|----------------|
| Engine Timing Mechanism: | Timing Chain |
| Evidence of Cam Belt Replacement: | Not Applicable |
| Replaced At (odometer reading): | |
| Road Conditions During Test Drive: | Dry |

General Comments

| Electrical | |
|--------------------------|-------------------------------------|
| Battery | <input checked="" type="checkbox"/> |
| Head lights | <input checked="" type="checkbox"/> |
| Tail lights | <input checked="" type="checkbox"/> |
| Indicators | <input checked="" type="checkbox"/> |
| Dashboard warning lights | <input checked="" type="checkbox"/> |
| Wipers (front & rear) | <input checked="" type="checkbox"/> |
| Window winder FL | <input checked="" type="checkbox"/> |
| Window winder FR | <input checked="" type="checkbox"/> |
| Window winder RL | <input checked="" type="checkbox"/> |
| Window winder RR | <input checked="" type="checkbox"/> |
| Rear view mirrors | <input checked="" type="checkbox"/> |
| Radio (basic test only) | <input checked="" type="checkbox"/> |
| CD (basic test only) | <input checked="" type="checkbox"/> |
| Reversing camera | <input type="checkbox"/> |

| Transmission & Drive | |
|----------------------|-------------------------------------|
| Operation | <input checked="" type="checkbox"/> |
| Noise | <input checked="" type="checkbox"/> |
| Clutch | <input type="checkbox"/> |
| CV joints | <input checked="" type="checkbox"/> |
| Wheel bearings | <input checked="" type="checkbox"/> |
| Wheel balance | <input checked="" type="checkbox"/> |
| Brakes | |
| Performance | <input checked="" type="checkbox"/> |
| Hand Brake | <input checked="" type="checkbox"/> |
| Keys & Locking | |
| Central locking | <input checked="" type="checkbox"/> |
| Remote locking | <input checked="" type="checkbox"/> |
| Number of keys | <input type="text" value="1"/> |

| Engine | |
|---------------------------|-------------------------------------|
| Oil level | <input checked="" type="checkbox"/> |
| Smoke & fumes | <input checked="" type="checkbox"/> |
| Performance | <input checked="" type="checkbox"/> |
| Noise | <input checked="" type="checkbox"/> |
| Cooling System | |
| Coolant condition | <input checked="" type="checkbox"/> |
| Performance | <input checked="" type="checkbox"/> |
| Radiator / Hoses (visual) | <input checked="" type="checkbox"/> |
| Suspension | |
| Suspension performance | <input checked="" type="checkbox"/> |
| Steering performance | <input checked="" type="checkbox"/> |
| Shock absorbers | <input checked="" type="checkbox"/> |

| Tyres (lowest observed tread depth) | |
|--|--|
| Left front | <input type="text" value="6"/> mm |
| Right front | <input type="text" value="6"/> mm |
| Left rear | <input type="text" value="7"/> mm |
| Right rear | <input type="text" value="7"/> mm |
| Spare | <input type="text" value="No"/> |
| Tools | <input checked="" type="checkbox"/> |
| Interior | |
| AC Operation | <input checked="" type="checkbox"/> |
| Heater fan | <input checked="" type="checkbox"/> |
| Seatbelts | <input checked="" type="checkbox"/> |
| Horn | <input checked="" type="checkbox"/> |
| Turners Certified Key | |
| <input checked="" type="checkbox"/> = Pass | <input checked="" type="checkbox"/> = Fail |
| <input type="checkbox"/> = Not applicable for this vehicle | |

Inspected by: John Lindsay Date: 31 Jan 2019

I have read and understood this condition guide. Name: Signature: