

Report ID: 18,886,026 Version: 1 01 Feb 2019 Created:

| Make: | Audi | Model: | A4 | Body Style: | Sedan | | Pass | Fail | N/A | |
|--|--------------------------|----------------------|------------------------|---------------------------------|----------------------|--|--------------|------|-----|--|
| Year: | 2005 | Registration: | DBU452 | Reg Expiry: | 01 Jul 2019 | Engine | | | | |
| WoF Expiry: | 10 Jan 2020 | Odometer: | 150,585 Kms | Good No: | 18886026 | Oil level | ~ | | | |
| VIN: | WAUZZZ8EX6A06905 | Next Service: | 164154 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | SSC | -0 | S SC S SC | -01- | SD | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | Transmission | | | |
| D = dent R = rust | s sc | | | 715 | HILL | Operation | ~ | | | |
| PT = paint defe | ect NP | F | | $\left[\left(\right) \right]$ | | Noise | ~ | | | |
| C = crack | | | | + | SC | Clutch | | | ~ | |
| P = pin dent | HID | | | | 세비 | CV joints | ~ | | | |
| * = decals | SPSC 916 | | | -No- | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs S SC S S SC S SC S SC S SC | | | | | | Performance | ~ | | | |
| Deduction | | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| Minor stone chips in the windscreen , | | | | | | Left front 4 mm | | | | |
| | | | | | | Right front | | 1 | mm | |
| | | | | | | Left rear | | 5 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | | 5 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | - | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | • | | | |
| | | | | | | Operation | ~ | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Average | | | | | Head lights | ~ | | | |
| | A | | | | | Tail lights | ~ | | | |
| Carpets | Average | | | | | Indicators | ~ | | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | | |
| | | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | ard Average | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | Window winder RL | ~ | | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 1 | | I | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | | | | |
| | uning res | | Dry | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | - | | ~ | |
| Evidence of Cam Belt Replacement: No Kms: | | | | | | Reversing camera | | | ~ | |
| L | | | | | | | | | | |
| Inspected by: Donovan Matara Date: 01 Feb 2019 | | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: