

Basic Vehicle Condition Guide

Report ID: 18,886,639

Pass

Version: 1

Engine

Created: 05 Feb 2019


Fail

N/A

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: 1999 Registration: DYP34 Reg Expiry: 29 Nov 2019 **Odometer:** WoF Expiry: 24 Apr 2019 94,400 Kms **Good No:** 18886639 VIN: WVWZZZ1JZXP23176: Next Service: 105000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Shocks soft

Interior Comment	<u>s</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Ac not cold Abs light on

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jeff Luke

Evidence of Cam Belt Replacement: No Kms:

Oil level	~		
Smoke & fumes	~		
Performance	\(\triangle \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.0	mm
Right front	4.0		mm
Left rear	5.0		mm
Right rear	5.0		mm
Spare		Yes	
Suspension			
Suspension performance		~	
Steering performance	~		
Shock absorbers		~	
Air Conditioning / Heater	ı		
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	l	1
Central locking	~		
Remote locking	~	~	

I have read and understood this condition guide.

Name:

Signature:

05 Feb 2019

1

Reversing camera