

Basic Vehicle Condition Guide

Report ID: 18,887,069


Version: 1

Created: 14 Feb 2019

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2014 Registration: HQL973 Reg Expiry: 29 Aug 2019 WoF Expiry: **Odometer:** 02 Oct 2019 108,010 Kms **Good No:** 18887069 VIN: MR0EZ12G104014298 Next Service: 108,000kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rear bumper plastic moulding missing near tow bar + dents

1 tray strap missing (left hand side)

Right tail light cracks

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Underbody surface rust

Interior Comm	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Ca Thach

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\(\times \)				
Performance	>				
Noise	'				
Cooling System					
Coolant condition	'				
Performance	~				
Radiator / Hoses (visual)	>				
Transmission					
Operation	~				
Noise	V V				
Clutch	~				
CV joints			~		
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread	depth	of tyre	es)		
Left front	9		mm		
Right front	9		mm		
Left rear	3		mm		
Right rear	4		mm		
Spare		Yes			
Suspension					
Suspension performance	>				
Steering performance	V				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	VVV				
Wipers (front & rear)					
Window winder FL	\(\times \)				
Window winder FR	~				
Window winder RL	~				
Window winder RR	V				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	3				
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Poversing camera					

I have read and understood this condition guide.

Name:

Signature:

14 Feb 2019

Reversing camera