

Basic Vehicle Condition Guide

Report ID: 18,888,056

Pass

~

~

/

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition Performance

Created: 07 Feb 2019


Fail

N/A

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2002 Registration: JMW376 **Reg Expiry:** 11 Aug 2019 WoF Expiry: **Odometer:** 25 Jan 2020 201,991 Kms **Good No:** 18888056 VIN: KMHSB81BR2U18416(Next Service: 207503 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments				
Seats	Poor			
Carpets	Poor			
Panels	Poor			
Dashboard	Poor			

General Comments

Gear selection poor

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Stuart Melbourne Inspected by:

Kms: 179,418

Name:

Radiator / Hoses (visual) Transmission Operation V Noise 1 Clutch V CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 6 mm Left rear 6 mm Right rear 6 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR 1 Window winder RL Window winder RR Rear view mirrors Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 1 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

07 Feb 2019

Signature:

Date:

ave reac	l and 11	nderstor	nd thic	condition	aniida