

Basic Vehicle Condition Guide

Report ID: 52,169


Version: 1

Created: 18 Feb 2019

Make: Model: Volkswagen Beetle **Body Style:** Hatchback Year: 2004 Registration: **GUJ913** Reg Expiry: 12 Jun 2019 WoF Expiry: **Odometer:** 22 Feb 2020 175,123 Kms **Good No:** 18889424 VIN: WVWZZZ9CZ4M5059(Next Service: 187000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Glovebox handle broken, unable to open LH wing mirror damaged Rear tyres edge worn

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No cambelt history RH outer CV boot split Oil leaks

| | Interior Comments | | | | | | | |
|--|-------------------|---------|--|--|--|--|--|--|
| | Seats | Average | | | | | | |
| | Carpets | Average | | | | | | |
| | Panels | Average | | | | | | |
| | Dashboard | Average | | | | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No Kms:

08 Feb 2019 Inspected by: **DM Motors** Date:

| | Pass | Fail | N/A |
|------------------------------|---|---------|-----|
| Engine | • | • | • |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | VVV | | |
| Noise | ~ | | |
| Cooling System | • | • | • |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | • | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | V | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | depth | of tyre | es) |
| Left front | Į. | 5 | mm |
| Right front | į | 5 | mm |
| Left rear | : | 2 | mm |
| Right rear | 1 | 2 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | | ~ | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |

I have read and understood this condition guide.

| Name: | | | |
|-------|--|--|--|
| | | | |