

					Left front		7
					Right front		7
					Left rear	7	
Conditions During Body Inspection: Dry					Right rear	7	
				Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension		
					Suspension performance	~	
					Steering performance	~	
					Shock absorbers	~	
					Air Conditioning / Heater		1
	_				Operation	~	
					Electrical / Accessories		
	Seats	Good			Head lights	~	
	<u> </u>	Average			Tail lights	~	
	Carpets	-			Indicators	~	
	Panels	Good			Dashboard warning lights	~	
		Good			Wipers (front & rear)	V	
	Dashboard				Window winder FL	~	
					Window winder FR	~	
<u>General Comments</u>					Window winder RL	~	
					Window winder RR	~	
					Rear view mirrors	V	
					Radio (basic test only)	~	
					CD (basic test only)	~	
					Number of keys	1	
	Road Conditions D	uring Test Drive: [	Dry		Central locking	~	
			•		Remote locking	~	
Engine Timing Mechanism: Cambelt				Sat. Nav. (basic test only)			
	Evidence of Cam Be	elt Replacement: No	0	Kms:	Reversing camera		
_	Inspected by: Jaso	n Law			Date: 14 Feb 20	19	

I have read and understood this condition guide.

Name: .....

Signature: .....

~ ~

2

Pass

V

V

V

V

V

V

V

V

V

V

V

V

V

14 Feb 2019

Fail

N/A

V

mm mm mm mm