

Report ID: 18,892,481 Version: 5 13 Aug 2019 Created:

Make:	Mercedes-Benz	Model:	C300	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	HNL47	Reg Expiry:	26 Sep 2019	Engine			
WoF Expiry:	26 Sep 2019	Odometer:	182,087 Kms	Good No:	18892481	Oil level	~		
VIN:	WDD2040542A20960!	Next Service:	192092	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is goods	for one and miles as	Danta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints			~
* = decals	- MIK			- NL	EITR	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Noto: com	L defects & blemishes		laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-		
L/H fog light broken. R/H wing mirror indicator lens cracked.						Tyres (lowest observed tread depth of tyres)			
R/H wing mirror indicator lens cracked. Chipped screen.						Left front		.0	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	inet inspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
	-					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
OK.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
			·			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 13 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: