

 Report ID:
 18,892,826

 Version:
 1

 Created:
 12 Feb 2019

Make:	Holden	Model:	Malibu	Body Style:	Sedan		Pass	Fail	N/A
Year:	2014 Registration: HUB509 Reg Expiry: 04 Mar 2019				Engine				
WoF Expiry:	22 Dec 2019	Odometer:	67,939 Kms	Good No:	18892826	Oil level	~		
VIN:	KL3GA69U9EB064585	Next Service:	71703	Service Histor	r y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside		for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and t	his can be arranged ic	or an additional	charge.	Coolant condition	~		
	SC		SC		DP	Performance	~		
Key: S = scratch		=		5(0)-		Radiator / Hoses (visual)	~		
D = dent	TE				An	Transmission			
R = rust				20	E SD	Operation	~		
PT = paint defe	ect NP				1111	Noise	~		
C = crack					S	Clutch			~
P = pin dent	sc de				2414	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC W	E	PT P W		DW	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
<u></u>						Tyres (lowest observed tread depth of tyres)			
						Left front		3	mm
						Right front	1	2	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deckle	rd Good					Wipers (front & rear)	~		
Dashboa	iu l					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Jason Law Date: 12 Feb 2019									

I have read and understood this condition guide.

Name:

Signature:

.