

Basic Vehicle Condition Guide

Report ID: 18,893,782


Version: 2

Created: 14 Feb 2019

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2010 Registration: FJD689 Reg Expiry: 29 Jul 2019 **Odometer:** WoF Expiry: 15 Jun 2019 180,579 Kms **Good No:** 18893782 VIN: MMAJNKA40AD01272 Next Service: 177400 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LR and RR reflection lens cracked RF tyre camber wear

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Rust spot on Sub frame Underbody rusty

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

Dry

General Comments

Inspected by:

Remote key not working Clutch need attention (too high)

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Bobby Zhong

Kms:

| | Pass | Fail | N/A | |
|------------------------------|-----------------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | V V | | | |
| Noise | ~ | | | |
| Cooling System | | • | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | ! | • | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | ~ | | | |
| CV joints | | | ~ | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed treac | depth | of tyre | es) | |
| Left front | 3 | 3 | mm | |
| Right front | 1 | .6 | mm | |
| Left rear | 2 | | mm | |
| Right rear | 2 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | V V V V V | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | \(\times \) | | | |
| Radio (basic test only) | _ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | L | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature:

14 Feb 2019

Reversing camera