


Make:	Mazda	Model:	Bt-50	Body Style:	Utility
Year:	2010	Registration:	FLL19	Reg Expiry:	20 Jun 2019
WoF Expiry:	17 Oct 2019	Odometer:	286,087 Kms	Good No:	18895431
VIN:	MM0UNY0E40085772	Next Service:	288000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Surface rust on front of tray headboard in behind cab. Aerial bent. Stonechips on windscreen. 2 holes in roof from wiring. Dents under roof rack on roof
Glovebox damaged. Screw holes in dash and console . Switch blanks missing in dash. Rear seat lower squabs missing. Screw holes in rear cab panel.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

LR axle seal has oil seepage. Damage on RR mudflap.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

LF flare missing on bumper. Chrome trim on bonnet loose on RHS. Holes from aerial mounts on both front guards.
Wear on both front seats. Wear on RF seatbelt. Wear on both front door switches . No towball.
Slight shudder in clutch.
Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 200,000

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	6	mm	
Left rear	4	mm	
Right rear	5	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 13 Feb 2019

I have read and understood this condition guide.

Name:

Signature: