

Basic Vehicle Condition Guide

Report ID: 18,895,859


Version:

Created: 14 Feb 2019

Make: Model: Great Wall V-Series **Body Style:** Utility Year: 2012 Registration: **GNT569** Reg Expiry: 11 Dec 2017 WoF Expiry: **Odometer: Good No:** 153,016 Kms 18895859 VIN: **Next Service:** LGWDBE173CC64297 155,900kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

R/H tail light out & scuffed.

Chipped screen. Wheel centre caps missing.

No spare wheel or jack & tools. Tow bar, but no tongue or ball. Repainted, some defects

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Seepage around steering box.

| Interior Comments | | | | |
|-------------------|-------------------------------|--|--|--|
| Seats | worn & holes in drivers seat. | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Not selecting 4WD low.

Inspected by:

ABS light on.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No Kms:

Name:

| Date: | 14 Feb 201 | 9 |
|-------|------------|---|

| | | Pass | Fail | N/A | | | |
|--|--|---------------------------------------|--------------|----------|--|--|--|
| Engine | | | | | | | |
| | Oil level | > | | | | | |
| | Smoke & fumes | ✓ | | | | | |
| ıſ | Performance | / | | | | | |
| | Noise | 1 | | | | | |
| | Cooling System | | | | | | |
| | Coolant condition | ' | | | | | |
| ıt | Performance | ~ | | | | | |
| lŀ | Radiator / Hoses (visual) | ~ | | | | | |
| ╟ | Transmission | | | | | | |
| ╟ | Operation | | ~ | | | | |
| lŀ | Noise | ~ | | | | | |
| ╟ | Clutch | · · | | | | | |
| ╟ | CV joints | · · | | | | | |
| ╟ | - | • | | | | | |
| Wheel bearings 🗸 | | | | | | | |
| | Brakes Performance | | | | | | |
| ŀ | | • | | | | | |
| | Hand Brake | / | - c · | | | | |
| | Tyres (lowest observed tread depth of tyres) | | | | | | |
| ╟ | Left front | 7 | 7 | mm | | | |
| | Right front | 6 | | mm | | | |
| | Left rear | 6 | | mm | | | |
| | Right rear | 6 mm | | | | | |
| il | Spare | No | | | | | |
| ֓֞֜֜֟֜֜֟֝֓֓֓֓֓֓֓֓֓֓֓֟֜֟֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓ | Suspension | | ı | | | | |
| | Suspension performance | > | | | | | |
| | Steering performance | ' | | | | | |
| | Shock absorbers | ~ | | | | | |
| | Air Conditioning / Heater | | | | | | |
| il | Operation | ' | | | | | |
| | Electrical / Accessories | | | | | | |
| | Head lights | ~ | | | | | |
| | Tail lights | > | | | | | |
| | Indicators | ~ | | | | | |
| | Dashboard warning lights | ~ | | | | | |
| | Wipers (front & rear) | ~ | | | | | |
| | Window winder FL | ~ | | | | | |
| ! | Window winder FR | ~ | | | | | |
| lŀ | Window winder RL | > > > > > > > > > > > > > > > > > > > | | | | | |
| lŀ | Window winder RR | ~ | | | | | |
| lŀ | Rear view mirrors | | ~ | | | | |
| ╟ | Radio (basic test only) | ~ | | | | | |
| ╟ | CD (basic test only) | ~ | | | | | |
| ╟ | Number of keys | 1 | l | I | | | |
| ıŀ | Central locking | · · | | | | | |
| | Remote locking | | | 1 | | | |
| ╟ | Sat. Nav. (basic test only) | | | ., | | | |
| H | Reversing camera | | | ., | | | |
| L | neversing carriera | | | | | | |
| Date: 14 Feb 2019 | | | | | | | |

Signature: