

Basic Vehicle Condition Guide

Report ID: 18,897,280


Version: 1

Created: 20 Feb 2019

Make: Model: Honda City **Body Style:** Hatchback Year: 1986 Registration: PN5475 Reg Expiry: 01 Apr 2019 **Odometer:** WoF Expiry: 27 Aug 2019 93,050 Kms **Good No:** 18897280 VIN: **Next Service:** 95,510 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

Interior Comments			
Seats	drivers seat ripped rest good		
Carpets	Average		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 64,000

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	V			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	'			
Performance	~			
Radiator / Hoses (visual)	>			
Transmission				
Operation	~			
Noise	~			
Clutch	v v			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	4	.6	mm	
Right front	3	.7	mm	
Left rear	5	.4	mm	
Right rear	3.9		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \) \(\t			
Window winder FL	~			
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	2	ı		
Central locking			~	
Remote locking			<i>V V</i>	
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature:

Inspected by: lan Dunn Date: 14 Feb 2019

Name: