

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Coolant condition Performance PT D S Key: Radiator / Hoses (visual) S = scratch Fransmission D = dent SW S SC W Operation V R = rustNoise PT = paint defect PT C = crackClutch P = pin dent CV joints SC * = decals Wheel bearings SC = stone chips Brakes W = significant scuffs SD PT W Performance Note: some defects & blemishes may not be displayed in the diagram Hand Brake **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Windscreen chips Left front **Right front** Left rear **Right rear** Conditions During Body Inspection: Dry Spare Under Carriage & Under Bonnet Inspection Comments Suspension Engine oil leaks Suspension performance Steering performance V Radiator hoses starting to perish Shock absorbers Air Conditioning / Heater Operation Interior Comments Electrical / Accessories Average Head lights Seats V Tail lights Average Carpets Indicators Average Dashboard warning lights Panels V Wipers (front & rear) Average Dashboard Window winder FL Window winder FR **General Comments** Window winder RL A/C not cold Window winder RR Uneven idle Rear view mirrors Radio (basic test only)

V V 1 V CD (basic test only) Number of keys 1 V Central locking **Road Conditions During Test Drive:** Dry Remote locking

96,191

Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes

Greg Morgan

Inspected by:

15 Feb 2019 Date:

Sat. Nav. (basic test only)

Reversing camera

Name:

Kms:

I have read and understood this condition guide.

Signature:

Report ID: 18,897,897 Version: 1 Created: 15 Feb 2019

Pass

~

V

V

V

V

V

~

V

~

V

6.0

3.0

5.0

3.0

V

~

1

~

1

V

V

Yes

V

V

V

mm

mm

mm

mm

V

1

V

~

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail