

Basic Vehicle Condition Guide

Report ID: 18,897,995


Version: 3

Created: 13 Mar 2019

Make: Model: Nissan Navara **Body Style:** Utility Year: 2010 Registration: FFE387 Reg Expiry: 01 Jul 2019 WoF Expiry: **Odometer:** 11 Mar 2020 173,454 Kms **Good No:** 18897995 VIN: MNTVCUD40A000394 Next Service: 178,100 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 13 Mar 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>v</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5	.0	mm
Right front	6.0		mm
Left rear	6.0		mm
Right rear	5.0 m		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories		1	1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	VVV		
Window winder FL	~		
Window winder FR	~		
Window winder RL	\(\times \)		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			1
Reversing camera			V

Signature: