

Exhaust mount damaged, needs repair.		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater		
		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Average	Head lights	~	
Compate	Good	Tail lights	~	
Carpets		Indicators	~	
Panels	Good	Dashboard warning lights	~	
	Good	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
		Window winder FR	~	
General Comments		Window winder RL	~	
Drives well.		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
	CD (basic test only)	~		
		Number of keys	1	
Road Conditions During Test Drive: Dry		Central locking	~	
		Remote locking	~	
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera		~
Inspected by: Roger King Date: 19 Feb 2019				

Name: .....

Report ID: 18,898,451

Pass

V

V

V

V

V V

V

V

V

V

V

~

V

5

6

6

7

Yes

1

19 Feb 2019

Fail

N/A

V

mm

mm

mm

mm

Version:

Created: