



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	18,898,839
Version:	2
Created:	06 Sep 2019

Make:	Mazda	Body Style:	Wagon
Model:	CX-5	VIN:	7AT0C144X19126962
Year:	2013	Odometer:	99,209 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good								
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good								
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good						
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good							
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	4	mm	62	Right Front	6	mm	86	L/H Mirror	Good						
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	5	mm	64	Right Rear	5	mm	87	L/F Guard	Good						
7	Rear Right Indicators	✓	36	Clutch	•	65	Spare	No	66	Tools	✓	88	R/F Guard	Good								
8	Rear Left Indicators	✓	37	CV Joints	✓	67	AC Operation	✓	68	Heater Fan	✓	89	L/H Doors	Good								
9	Reversing Lights	✓	38	Wheel Bearing	✓	69	Seatbelts	✓	70	Horn	✓	90	R/H Doors	Good								
10	Rear Reflectors	✓	39	Wheel Balance	✓	71	Seat Heaters	•	72	Sun Visors	✓	91	L/H Sill	Good								
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	92	R/H Sill	Good								
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	75	Carpets	Good	76	Panels	Good	93	Boot/Tail Gate	Good								
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	77	Dashboard	Good	78	Fuel Cap	✓	94	Front Bumper	Good								
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)					79	Mud Flaps	✓	95	Rear Bumper	Good								
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	80	Fuel Cap	✓	96	Roof	Good							
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	69	Seatbelts	✓	81	Wipers Front/Rear	✓	97	Bonnet	Good					
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	70	Horn	✓	82	Window Opener FL	✓	98	Fuel Cap	✓					
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	71	Seat Heaters	•	83	Window Opener FR	✓	99	Mud Flaps	✓					
19	Rev Counter	✓	Keys and Locking		47	Central Locking	✓	71	Seat Heaters	•	72	Sun Visors	✓	84	Window Opener RL	✓	100	WOF	✓			
20	Fuel Gauge	✓	48	Remote Locking	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	74	Window Opener RR	✓	85	Rear View Mirrors	✓					
21	Wipers Front/Rear	✓	49	Number of Keys	2	49	Number of Keys	2	75	Carpets	Good	76	Radio (Basic Test Only)	✓	86	CD (Basic Test Only)	✓					
22	Window Opener FL	✓	Engine		50	Oil Level	✓	50	Oil Level	✓	77	Dashboard	Good	27	Radio (Basic Test Only)	✓	28	CD (Basic Test Only)	✓			
23	Window Opener FR	✓	51	Smokes and Fumes	✓	51	Smokes and Fumes	✓	52	Performance	✓		29	Boot Open Switch	✓	29	Boot Open Switch	✓				
24	Window Opener RL	✓	52	Performance	✓	52	Performance	✓	53	Noise	✓											
25	Window Opener RR	✓	53	Noise	✓	53	Noise	✓	54	Starter Motor	✓											
26	Rear View Mirrors	✓	54	Starter Motor	✓	54	Starter Motor	✓														

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	06 Sep 2019
---------------	------------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--