

Report ID: 18,899,403 Version: 1 19 Feb 2019 Created:

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2007	Registration:	EDW591	Reg Expiry:	30 Jun 2019	Engine	1	1	I
WoF Expiry:		Odometer:	103,631 Kms	Good No:	18899403	Oil level	~		
VIN:	WF0HXXGAJH7T5731	Next Service:	108500	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
				·		Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	SC		S P		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S D PT			210	HIVS	Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	PT SC				24116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – signincan	SC W		S P			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Slight paint fade on bonnet and front bumper.						Tyres (lowest observed tread depth of tyres)			
					Left front	2	.0	mm	
						Right front	2	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear	7	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
/						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachhar	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking		~	
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspecto	Inspected by: Chris Buckley Date: 18 Feb 2019								
Inspected by. Chris buckley Date: 10 reb 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....