

Report ID: 18,899,517 Version: 1 Created: 21 Feb 2019

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	1996	Registration:		Reg Expiry:	10 Nov 2019	Engine	1	I	1
WoF Expiry:	07 Apr 2019	Odometer:	139,665 Kms	Good No:	18899517	Oil level	~		
VIN:	7A88G610705123225	Next Service:	144,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and the	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SC S PT		ls	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	6/6				S SC W	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+		Clutch			~
P = pin dent	Ho				JUII ——	CV joints	~		
* = decals	SD QIC				ELIP SC	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs PT SC SC PT SC PT SC W D									
							~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	nayed in the diagram	Hand Brake		. (.	
Left side body skirt cracked						Tyres (lowest observed tread depth of tyres)			
						Left front		.9	mm
						Right front		.9	mm
[Left rear		.2	mm
Conditions During Body Inspection: Dry						Right rear	6.4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	irriage & Under Bor	inet inspectic	on Comments			Suspension		1	
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
					-	Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	4	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
									1
Inspecte	Inspected by: Ian Dunn Date: 18 Feb 2019								

I have read and understood this condition guide.

Name:

Signature: