

Basic Vehicle Condition Guide

Report ID: 52,199


Version: 1

Created: 18 Mar 2019

Make: Model: **Body Style:** Toyota Hilux Utility Year: 2006 Registration: DHT827 Reg Expiry: 26 Jun 2019 **WoF Expiry: Odometer: Good No:** 19 Mar 2020 306,090 Kms 19105079 VIN: MR0EZ12G404002808 Next Service: Just Serviced Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 300,909

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\(\times \) \(\t		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	2s)
Left front	4	1	mm
Right front	4	1	mm
Left rear	4		mm
Right rear	4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			1

Signature:

Inspected by: J Ottesen Date: 05 Mar 2019

Name: