

Report ID: 1,211 Version: 2 26 Mar 2019

Created:

Make:	Toyota	Model:	Avensis	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	GNE383	<b>Reg Expiry:</b>	11 Jul 2019	Engine			
WoF Expiry:	11 Mar 2020	Odometer:	136,530 Kms	Good No:	19105098	Oil level	~		
VIN:	7AT0H63MX12003685	Next Service:	Just serviced	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0	<u>s</u>	-01-		Radiator / Hoses (visual)	r		
S = scratch						Transmission			L
D = dent R = rust	s dir			210	HILD	Operation	V		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	V		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	HID				2414	CV joints	V		
* = decals	- Alf			-Jul		Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs						Performance	~		
Podylaca	action Commonts	Note: som	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	25)
						Left front 5.0 mm			
						Right front	-	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection:						Right rear			mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		$\left  - \right $
Panels	Good					Dashboard warning lights	~		$\left  - \right $
		Crad				Wipers (front & rear)	~		$\left  - \right $
Dashboa	rd Good					Window winder FL	~		$\left  - \right $
						Window winder FR	~		$\left  - \right $
General C	<u>Comments</u>					Window winder RL	~		$\left  - \right $
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	~		-
			ЛУ			Remote locking	~		
Engine Tir	ning Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	~		$\left  - \right $
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	v v		
Inspected by: J Offesen Date: 05 Mar 2019									

I have read and understood this condition guide.

Name: .....