

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Coolant condition Performance D W D Key: Radiator / Hoses (visual) S = scratch Fransmission D = dent S SC Operation R = rustNoise PT = paint defect C = crackClutch P = pin dent CV joints SC * = decals D Wheel bearings SC = stone chips Brakes W = significant scuffs W SP Performance Note: some defects & blemishes may not be displayed in the diagram Hand Brake **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) RR, FL windows not working from door switches Left front **Right front** Left rear **Right rear** Conditions During Body Inspection: Dry Spare Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance Steering performance Shock absorbers Air Conditioning / Heater Operation Interior Comments Electrical / Accessories Good Head lights Seats Tail lights Good Carpets Indicators Good Dashboard warning lights Panels

Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Remote key button missing Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 1 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) ~ Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera V Inspected by: Mathew Varghese

Name:

I have read and understood this condition guide.

23 May 2019 Date:

Signature:

Report ID: 19,105,675 Version: 4 23 May 2019 Created:

Pass

~

V

V

V

V

V

V

V

~

V

V

V

4

5

4

4

V

V

~

V

1

~

~

1

Yes

Engine

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A

V

mm

mm

mm

mm