

# **Basic Vehicle Condition Guide**

Report ID: 56,502

Version: 1

Created: 18 Mar 2019

Pass


Fail

N/A

Make: Model: Ford Fiesta **Body Style:** Hatchback Year: 2007 Registration: EBZ727 Reg Expiry: 13 Jul 2019 **Odometer:** WoF Expiry: 27 Mar 2020 293,011 Kms **Good No:** 19106828 VIN: WF0HXXGAJH7Y1834 Next Service: **Service History:** 

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Left Toil Lamp Lense Crodeed Bumper cracked **Tow Cover Missing** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Wet

## **Under Carriage & Under Bonnet Inspection Comments**

Left front tyre worn out Service due Oil Weeps from motor

No evidence of cambelt replacement

Right front tyre worn out

| Interior Comments |         |  |  |
|-------------------|---------|--|--|
| Seats             | Average |  |  |
| Carpets           | Average |  |  |
| Panels            | Average |  |  |
| Dashboard         | Average |  |  |

### **General Comments**

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No Kms:

| Engine                       |  |         |    |
|------------------------------|--|---------|----|
| Oil level                    | ~  |         |    |
| Smoke & fumes                | \( \times \)   |         |    |
| Performance                  | ~  |         |    |
| Noise                        | ~  |         |    |
| Cooling System               |  | •       |    |
| Coolant condition            | ~  |         |    |
| Performance                  | ~  |         |    |
| Radiator / Hoses (visual)    | ~  |         |    |
| Transmission                 |  |         |    |
| Operation                    | ~  |         |    |
| Noise                        | ~  |         |    |
| Clutch                       | ~  |         |    |
| CV joints                    | \( \times \)   |         |    |
| Wheel bearings               | ~  |         |    |
| Brakes                       |  | •       |    |
| Performance                  | ~  |         |    |
| Hand Brake                   | ~  |         |    |
| Tyres (lowest observed tread | depth  | of tyre | s) |
| Left front                   | (  | 0       | mm |
| Right front                  | (  | 0       | mm |
| Left rear                    | 4  | 4       | mm |
| Right rear                   | 4  | 4       | mm |
| Spare                        |  | Yes     |    |
| Suspension                   |  |         |    |
| Suspension performance       | ~  |         |    |
| Steering performance         | ~  |         |    |
| Shock absorbers              | ~  |         |    |
| Air Conditioning / Heater    |  |         |    |
| Operation                    | ~  |         |    |
| Electrical / Accessories     |  |         |    |
| Head lights                  | ~  |         |    |
| Tail lights                  | ~  |         |    |
| Indicators                   | ~  |         |    |
| Dashboard warning lights     | <b>V</b>   |         |    |
| Wipers (front & rear)        |  |         |    |
| Window winder FL             | ~  |         |    |
| Window winder FR             | ~  |         |    |
| Window winder RL             | ~  |         |    |
| Window winder RR             | \( \times \) \( \t |         |    |
| Rear view mirrors            | ~  |         |    |
| Radio (basic test only)      | ~  |         |    |
| CD (basic test only)         | ~  |         |    |
| Number of keys               | 2  |         |    |
| Central locking              | ~  |         |    |
| Remote locking               |  | ~       |    |
| Sat. Nav. (basic test only)  |  |         | ~  |

08 Mar 2018 Inspected by:

1

Reversing camera