



# Turners Certified Imports 50 Point Check

Report ID: 19,106,892  
Version: 1  
Created: 04 Mar 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Honda Body Style: Hatchback  
Model: FIT Odometer: 93,911 Kms  
Year: 2016 VIN: 7AT08G2YX19213607

### Under Carriage & Under Bonnet Inspection Comments

### General Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

### Electrical

|                          |                                     |
|--------------------------|-------------------------------------|
| Battery                  | <input checked="" type="checkbox"/> |
| Head lights              | <input checked="" type="checkbox"/> |
| Tail lights              | <input checked="" type="checkbox"/> |
| Indicators               | <input checked="" type="checkbox"/> |
| Dashboard warning lights | <input checked="" type="checkbox"/> |
| Wipers (front & rear)    | <input checked="" type="checkbox"/> |
| Window winder FL         | <input checked="" type="checkbox"/> |
| Window winder FR         | <input checked="" type="checkbox"/> |
| Window winder RL         | <input checked="" type="checkbox"/> |
| Window winder RR         | <input checked="" type="checkbox"/> |
| Rear view mirrors        | <input checked="" type="checkbox"/> |
| Radio (basic test only)  | <input checked="" type="checkbox"/> |
| CD (basic test only)     | <input checked="" type="checkbox"/> |
| Reversing camera         | <input type="checkbox"/>            |

### Transmission & Drive

|                |                                     |
|----------------|-------------------------------------|
| Operation      | <input checked="" type="checkbox"/> |
| Noise          | <input checked="" type="checkbox"/> |
| Clutch         | <input type="checkbox"/>            |
| CV joints      | <input checked="" type="checkbox"/> |
| Wheel bearings | <input checked="" type="checkbox"/> |
| Wheel balance  | <input checked="" type="checkbox"/> |

### Brakes

|             |                                     |
|-------------|-------------------------------------|
| Performance | <input checked="" type="checkbox"/> |
| Hand Brake  | <input checked="" type="checkbox"/> |

### Keys & Locking

|                 |                                     |
|-----------------|-------------------------------------|
| Central locking | <input checked="" type="checkbox"/> |
| Remote locking  | <input checked="" type="checkbox"/> |
| Number of keys  | 1                                   |

### Engine

|               |                                     |
|---------------|-------------------------------------|
| Oil level     | <input checked="" type="checkbox"/> |
| Smoke & fumes | <input checked="" type="checkbox"/> |
| Performance   | <input checked="" type="checkbox"/> |
| Noise         | <input checked="" type="checkbox"/> |

### Cooling System

|                           |                                     |
|---------------------------|-------------------------------------|
| Coolant condition         | <input checked="" type="checkbox"/> |
| Performance               | <input checked="" type="checkbox"/> |
| Radiator / Hoses (visual) | <input checked="" type="checkbox"/> |

### Suspension

|                        |                                     |
|------------------------|-------------------------------------|
| Suspension performance | <input checked="" type="checkbox"/> |
| Steering performance   | <input checked="" type="checkbox"/> |
| Shock absorbers        | <input checked="" type="checkbox"/> |

### Tyres (lowest observed tread depth)

|             |                                     |
|-------------|-------------------------------------|
| Left front  | 8 mm                                |
| Right front | 8 mm                                |
| Left rear   | 8 mm                                |
| Right rear  | 8 mm                                |
| Spare       | N/A                                 |
| Tools       | <input checked="" type="checkbox"/> |

### Interior

|              |                                     |
|--------------|-------------------------------------|
| AC Operation | <input checked="" type="checkbox"/> |
| Heater fan   | <input checked="" type="checkbox"/> |
| Seatbelts    | <input checked="" type="checkbox"/> |
| Horn         | <input checked="" type="checkbox"/> |

### Turners Certified Key

✓ = Pass X = Fail  
• = Not applicable for this vehicle

Inspected by: Mathew Varghese

Date: 27 Feb 2019

I have read and understood this condition guide.

Name: .....

Signature: .....