


<b>Make:</b> Foton	<b>Model:</b> Tunland	<b>Body Style:</b> Utility
<b>Year:</b> 2013	<b>Registration:</b> LTF227	<b>Reg Expiry:</b> 24 Apr 2019
<b>WoF Expiry:</b> 15 Nov 2019	<b>Odometer:</b> 143,056 Kms	<b>Good No:</b> 19106956
<b>VIN:</b> LVAV2MBB4DJ027053	<b>Next Service:</b>	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
 D = dent  
 R = rust  
 PT = paint defect  
 C = crack  
 P = pin dent  
 \* = decals  
 SC = stone chips  
 W = significant scuffs


**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Aerial mounted on LF guard. Damage on rear bumper. Damage on tear of RR guard. Both rear mudflaps missing. Has jack, no tools. RH indicator repeater lamp in mirror is damaged. Stonechips on windscreen. Screw holes in dash and console. Damage on console lid. Wear on steering wheel. Wear on RF seat.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Front diff has oil seepage. LR axle seal has oil seepage.

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**

Engine surging at idle. Gearbox is noisy and notchy changing into some gears. Lens damaged on LH spotlamp. Fuel flap release lever not secure. Screw covers missing on both front handles on A pillars.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise		✓	
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	3	mm	
Right front	3	mm	
Left rear	2	mm	
Right rear	8	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 08 Apr 2019

I have read and understood this condition guide. Name: ..... Signature: .....