

Report ID: 19,110,021 Version: 4 08 Mar 2019 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	Registration:	HYK229	Reg Expiry:	29 Jan 2020	Engine			<u> </u>
WoF Expiry:		Odometer:	108,970 Kms	Good No:	19110021	Oil level	~		
VIN:	7AT0DH6MX1410999(Next Service:		Service Histor		Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty	aration is made	for and milaan	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)			~
S = scratch D = dent						Transmission			<u> </u>
D = dent R = rust	sc			715	HIVS	Operation	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	sc gle			10		Wheel bearings			~
SC = stone chips W = significant scuffs						Brakes			
			S			Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front 4.0			mm
						Right front	4.0 mm		mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Wet						Right rear	4.0 mm		
						Spare	pare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Not hoisted	I					Suspension performance	~		
						Steering performance	~		
						Shock absorbers			~
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	_					Window winder FR	~		
General Comments					Window winder RL	~			
CD player n	ot working					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Xinghui Lin Date: 07 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: