

Report ID: 19,110,148 Version: 1 01 Mar 2019 Created:

Make:	Daihatsu	Model:	Sirion	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2007	Registration:	EGH135	Reg Expiry:	23 Apr 2019	Engine			1	
WoF Expiry:		Odometer:	69,257 Kms	Good No:	19110148	Oil level	~			
VIN:	JDAM301S001068315	Next Service:		Service Histor	y: No	Smoke & fumes	~		<u> </u>	
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
	W		S D S		S D	Performance	~			
Key:		-0	SD S		30	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	PT SC			715	S PT	Operation	~			
PT = paint defe		r I		$\left[ \left( \right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~			
* = decals	s alt			To .	ELC'S	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w – significan			SDW SD		S D	Performance	~			
Body Incr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Driver wing mirror cover damaged						<b>Tyres</b> (lowest observed tread depth of tyres)			25)	
	,					Left front	6	5	mm	
						Right front	3	3	mm	
						Left rear	6	5	mm	
Conditions During Body Inspection: Dry						Right rear	5 mn		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Comoto	left rear ca	irpet stain				Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
Deal-L	Average					Wipers (front & rear)	~			
Dashboa	iiu ý					Window winder FL	~			
	_					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
		<b>T</b> ''				Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: John Lindsay Date: 01 Mar 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....