

Report ID: 19,111,217 Version: 2 11 Mar 2019 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015		KFL332	Reg Expiry:	09 Apr 2019	Engine			
WoF Expiry:		Odometer:	102,834 Kms	Good No:	19111217	Oil level	~		
VIN:	JM0BM523810149763		102,05 114115	Service Histor	-	Smoke & fumes	~		
	511105111525010117705					Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Cooling System			
						Coolant condition Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		~
S = scratch									
D = dent	s sc all			1 - L	HID				
R = rust				10	SHIK	Operation	~		
PT = paint defe	ect					Noise	~		
C = crack P = pin dent	III		لسار			Clutch			~
* = decals	SC DIC				THE	CV joints	~		<u> </u>
SC = stone chi	ps U	10		10		Wheel bearings			~
W = significant scuffs						Brakes			
				S		Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5		mm
						Right front	5		mm
						Left rear	4		mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Not hoisted	I					Suspension performance	~		
						Steering performance	~		
						Shock absorbers			V
						Air Conditioning / Heater	11		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Cood					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
			2						
Road Conditions During Test Drive: Dry						Central locking	v		
Enaine Tir	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
		Nerrer N		11113.		Reversing camera	~		<u> </u>
Inspected by: Bobby Zhong Date: 11 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: