



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,112,671
Version:	2
Created:	06 Sep 2019

Make:	Nissan	Body Style:	Wagon
Model:	Murano	VIN:	7AT0DH74X19005946
Year:	2010	Odometer:	117,329 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•								
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good									
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good							
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good							
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good									
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	4	mm	84	Rear Wiper Blade	Good						
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>3</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>4</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	3	mm	63	Left Rear	4	mm	85	R/H Mirror	Good				
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>5</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	5	mm	65	Spare	Yes	86	L/H Mirror	Good					
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good	88	R/F Guard	Good						
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	89	L/H Doors	Good	90	R/H Doors	Good				
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td><td>92</td><td>R/H Sill</td><td>Good</td></th>	69	Seatbelts	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	91	L/H Sill	Good	92	R/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	71	Seat Heaters	•	93	Boot/Tail Gate	Good	94	Front Bumper	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good			
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>75</td> <td>Carpets</td> <td>Average</td> <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td>	74	Seats	Average	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>78</td><td>Seats</td><td>Average</td><td>79</td><td>Carpets</td><td>Average</td><td>80</td><td>Panels</td><td>Average</td><td>81</td><td>Dashboard</td><td>Average</td></th>	46	Handbrake	✓ <td>78</td> <td>Seats</td> <td>Average</td> <td>79</td> <td>Carpets</td> <td>Average</td> <td>80</td> <td>Panels</td> <td>Average</td> <td>81</td> <td>Dashboard</td> <td>Average</td>	78	Seats	Average	79	Carpets	Average	80	Panels	Average	81	Dashboard	Average
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>82</td> <td>Seats</td> <td>Average</td> <td>83</td> <td>Carpets</td> <td>Average</td> <td>84</td> <td>Panels</td> <td>Average</td> <td>85</td> <td>Dashboard</td> <td>Average</td>	82	Seats	Average	83	Carpets	Average	84	Panels	Average	85	Dashboard	Average	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>86</td> <td>Seats</td> <td>Average</td> <td>87</td> <td>Carpets</td> <td>Average</td> <td>88</td> <td>Panels</td> <td>Average</td> <td>89</td> <td>Dashboard</td> <td>Average</td>	49	Number of Keys	2	86	Seats	Average	87	Carpets	Average	88	Panels	Average	89	Dashboard	Average
18	Odometer	✓	Engine		50	Oil Level	✓ <td>90</td> <td>Seats</td> <td>Average</td> <td>91</td> <td>Carpets</td> <td>Average</td> <td>92</td> <td>Panels</td> <td>Average</td> <td>93</td> <td>Dashboard</td> <td>Average</td>	90	Seats	Average	91	Carpets	Average	92	Panels	Average	93	Dashboard	Average	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>94</td><td>Seats</td><td>Average</td><td>95</td><td>Carpets</td><td>Average</td><td>96</td><td>Panels</td><td>Average</td><td>97</td><td>Dashboard</td><td>Average</td></th>	52	Performance	✓ <td>94</td> <td>Seats</td> <td>Average</td> <td>95</td> <td>Carpets</td> <td>Average</td> <td>96</td> <td>Panels</td> <td>Average</td> <td>97</td> <td>Dashboard</td> <td>Average</td>	94	Seats	Average	95	Carpets	Average	96	Panels	Average	97	Dashboard	Average
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>98</td><td>Seats</td><td>Average</td><td>99</td><td>Carpets</td><td>Average</td><td>100</td><td>Panels</td><td>Average</td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td>98</td> <td>Seats</td> <td>Average</td> <td>99</td> <td>Carpets</td> <td>Average</td> <td>100</td> <td>Panels</td> <td>Average</td> <td></td> <td></td> <td></td>	98	Seats	Average	99	Carpets	Average	100	Panels	Average			
21	Wipers Front/Rear	✓																		
22	Window Opener FL	✓																		
23	Window Opener FR	✓																		
24	Window Opener RL	✓																		
25	Window Opener RR	✓																		
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	06 Sep 2019
---------------	------------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--