

Report ID: 19,113,178 Version: 2 13 Mar 2019 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	EWG84	Reg Expiry:	18 Aug 2019	Engine			
WoF Expiry:	24 Dec 2019	Odometer:	221,011 Kms	Good No:	19113178	Oil level	~		
VIN:	6G1ZK54F25L534308	Next Service:	220000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	narge.	Coolant condition	~		
	S D PT		S			Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	scw			210		Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack				The second secon	R PT SC	Clutch			~
P = pin dent	s sc dl				2416	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significan	W	S	S			Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Rear parking sensors pushed in						Tyres (lowest observed tread depth of tyres)			
Driver side part of badge missing						Left front 5 n			mm
						Right front	5	5	mm
						Left rear	4	ŀ	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Taillight len	ises not matching one t	inted and one no	ot			Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	all seats w	orn				Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachhaa	rd Average					Wipers (front & rear)	~		
Dashboa	iu -					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	Central locking	~							
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 13 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: