

Basic Vehicle Condition Guide

Report ID: 19,114,689


Version: 2

Created: 02 Apr 2019

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2014 Registration: HKN363 Reg Expiry: 21 Aug 2019 WoF Expiry: **Odometer:** 25 Feb 2020 135,220 Kms **Good No:** 19114689 VIN: MMAJNKB40FD00416 Next Service: 142736 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen. Dent left rear cab corner. Dent right rear cab corner. Inner sills need painting. Hole in roof. Unable to adjust mirrors.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 128,079

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes	•	•	•
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	2.0		mm
Right front	3.0		mm
Left rear	5.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater		!	•
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors		~	
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	ı	-
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

Reversing camera

07 Mar 2019

Signature:

I have read and understood this condition guide. Name: