

Report ID: 56,509 Version: 2 21 Mar 2019 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008	Registration:	KSQ213	Reg Expiry:	17 Jul 2019	Engine			
WoF Expiry:	25 Mar 2020	Odometer:	88,260 Kms	Good No:	19115193	Oil level	~		
VIN:	WVWZZZ1KZ8M3296(Next Service:	Just Serviced	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	nis can be arranged fo	or an additional of	charge.	Coolant condition	~		
	SC					Performance	~		
Key:		$-\infty$		5(0)-		Radiator / Hoses (visua	I) 🖌		
S = scratch D = dent	AL	Transmission	Transmission						
R = rust	sc s			710	EIIVS	Operation	~		
PT = paint defe	ect NP	r I			17141	Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				7414	CV joints	~		<u> </u>
* = decals	MA			-Jos		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC						Performance	Performance 🖌		
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		1
Body Inspection Comments						Tyres (lowest observed t	Tyres (lowest observed tread depth of tyres)		
						Left front 8 n			
						Right front		8	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare	5		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performan	ce 🖌		
						Steering performance	· ·		
						Shock absorbers	· ·		
		Air Conditioning / Heat							
		Operation			1				
Interior Comments						Electrical / Accessories	•		
Seats	Good					Head lights	~		T
						Tail lights	· ·		+
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lig			
						Wipers (front & rear)	······································		+
Dashboa	Ird Good					Window winder FL	- V		+
						Window winder FR	· ·		
General Comments						Window winder RL			
						Window winder RR	· ·		+
						Rear view mirrors	v v		
						Radio (basic test only)	- V		
						CD (basic test only)	- V - V		+
						Number of keys	1		<u> </u>
						Central locking	· ·		1
Road Conditions During Test Drive: Dry						Remote locking	~ ~ ~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test onl			
-	of Cam Belt Replac	Reversing camera	y)		~ ~				
			10	Kms:					
Inspected by: Scott Date: 13 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: