

Report ID: 19,115,313 Version: 1 09 Apr 2019 Created:

Make:	Volvo	Model:	C30	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	KHL786	Reg Expiry:	21 Jul 2019	Engine			
WoF Expiry:	17 Jan 2020	Odometer:	70,735 Kms	Good No:	19115313	Oil level	~		
VIN:	YV1MK385982052748	Next Service:	Freshly Serviced	Service Histor	y: No	Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty		6	Danta harra nat	harry discounted and	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:	sc	-0	SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	EID S	Operation	~		
R = rust PT = paint def				Γ	JHIA	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	sc gig			AL.	EII PR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC						Performance V			
		Note: com	ne defects & blemishes			Hand Brake			
Body Insp	pection Comments	Note. son	le délects & blemisnes	s may not be disp	layed in the diagram			- f h m	•
					Tyres (lowest observed tread depth of tyres)				
						Left front	5.		mm
						Right front	5.		mm
r						Left rear	3.		mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
	mage & under bur	inet inspectic	on comments			Suspension			
· ·						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carrasta	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	<		
	, Good					Wipers (front & rear)	<		
Dashboa	ra					Window winder FL	<		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
·						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanismu Cambolt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Dion Mair Date: 11 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: