

Report ID: 19,117,011 Version: 3 16 May 2019 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Wagon |] | | Pass | Fail | N/A |
|--|------------------------|----------------------|----------------------|----------------|--------------------|--|-------------------|----------|--------|-----|
| Year: | 2010 | Registration: | FKT64 | Reg Expiry: | 28 Jul 2019 | Engine | Engine | | | 1 |
| WoF Expiry: | 06 May 2020 | Odometer: | 200,454 Kms | Good No: | 19117011 | Oil level | | ~ | | |
| VIN: | 6G1EK8EF1AL431423 | Next Service: | 210,500 | Service Histor | y: No | Smoke & f | umes | ~ | | |
| | | | | | | Performan | ice | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Dauta have not | haan dispersion of | Noise | | v | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | Coolant condition | | | |
| | | | | | | Performan | | · · | | |
| Key: | SC | -0 | P SC SC | | sc | | Hoses (visual) | • | | ~ |
| S = scratch | | | | | | Transmissio | . , | | | • |
| D = dent SC 6 6 5 | | | | | | | Operation | | | |
| R=rust | | | | | | Noise | | レ レ | | |
| PT = paint defects C = crack | ect | | | + | SC | Clutch | | • | | ~ |
| P = pin dent | Htc | KI | | | JUII — | Clutch CV joints | | | | - |
| * = decals | sc pp | | | | FILTR | | | | | ~ |
| SC = stone chips | | | | | | Wheel bearings Brakes | | | | ~ |
| W = significant scuffs SC SC S SC SC | | | | | | | | | | 1 |
| | | | | | | Performan | | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brak | - | ~ | | |
| 1 key remote not working, buttons torn | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | | 7. | 0 | mm |
| | | | | | | Right front | Right front | | 7.0 mm | |
| | | | | | | Left rear | | 2. | 0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear 5.0 | | | 0 | mm |
| | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Suspensio | n performance | ~ | | |
| | | | | | | Steering p | erformance | ~ | | |
| | | | | | | Shock absorbers | | | ~ | |
| | | | | | | Air Conditioning / Heater | | | | |
| | | | | | | Operation 🖌 | | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Seats | | | | | Head light | S | ~ | | |
| | Good | | | | | Tail lights | | ~ | | |
| Carpets | | | | | | Indicators | | ~ | | |
| Panels | Good | | | | | Dashboard | d warning lights | ~ | | |
| | Card | | | | Wipers (fro | | ~ | | | |
| Dashboa | ard Good | | | | | Window w | | ~ | | |
| | I | | | | | Window w | | · · | | |
| General C | <u>Comments</u> | | | | | Window w | | ~ | | |
| | | | | | | Window w | | v v | | |
| | | | | | | Rear view | | ~ | | |
| | | | | | | | ic test only) | • • | | |
| | | | | | | CD (basic t | | v v | | |
| | | | | | | | | | | |
| | | | | | | • I | Number of keys 2 | | | |
| Road Conditions During Test Drive: Wet | | | | | | Central loc | - | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Remote lo | - | ~ | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | | oasic test only) | | | ~ |
| | | chient. N | | 11113. | | Reversing | camera | | | ~ |
| Inspecte | d by: Mathew Varghe | se | | | | ח | ate: 09 May 201 | 19 | | |
| | - Sy. Matrice Vargine | | | | | | | - | | |

I have read and understood this condition guide.

Name:

Signature: