

Report ID: 56,510 Version: 1 20 Mar 2019 Created:

Make:	Audi	Model:	S3	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	Registration:	JER613	Reg Expiry:	31 Oct 2019	Engine	L		I
WoF Expiry:		Odometer:	108,652 Kms	Good No:	19117957	Oil level	~		
VIN:	WAUZZZ8P3CA06726	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	protion is most-	for any and miles	Darte have not	boop dismonthed an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The		Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	sc 916			The	EIIP I	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disr	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread	•	oftvre) (24
						Left front			
						Right front			 mm
						Left rear			mm
Canalitian	Dunin n De du la s		2			Right rear		-	
Conditions During Body Inspection: Dry						Right rear 4 mr Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						Operation 🖌			
Good						Head lights			1
Seats						Tail lights	レ レ		
Carpets	Good						~ ~		
	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~ ~		
Dashboa	rd Good					Window winder FL	~		
]	Window winder FL Window winder FR	~		
General (Comments					Window winder PK	~		
						Window winder RL	~ ~		
						Rear view mirrors	~ ~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
	distance Doright The	Duite				Central locking			
Road Conditions During Test Drive: Dry						Remote locking	ン ン		
Engine Ti	ming Mechanism:	Cambelt	t			-			
-	of Cam Belt Replac		lo	Kms:		Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Dion Date: 12 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: